

Kevin M. Shea Vice President Government Relations - NH 900 Elm Street, Suite 1922 Manchester, NH 03101 603-641-1667

November 20,2008

Kathryn M. Bailey, PE Telecommunications Division Director New Hampshire Public Utilities Commission 21 South Fruit Street, Suite 10 Concord, New Hampshire 03301



Dear Kate:

In accordance with the Commission's Electronic Report Filing (ERF) program, **FairPoint** Communications - NNE has electronically filed the Quality of Service report for October, 2008 and is also filling the attached paper copy.

There where (20) exchanges that **met/exceeded** a 2.5 customer troubles report rate for three **consecutive** months ending with the October, 2008 report. Attached is a breakdown of the remediation that **FairPoint** Communications is under taking in order to address the 20 effected exchanges.

Please call if you have any questions.

Sincerely,

Kevin M. Shea Attachments

cc: Meredith Hatfield

Karen Mead Jeff Allen Erin Austin

QUALITY OF SERVICE REPORT - NEW HAMPSHIRE

	FairPoint NNE Monthly Service Quality Report		A11.0 (0)		650	V.	150	V	- 1,2	-2450	100	12145,011	2-12	100	- 372-31	100000000000000000000000000000000000000
			Objective	Jan	Feb	Mar	Apr	May	June	July	Aug	Sept	Oct	Nov	Dec	YTD Cum.
Anex	aliation of Service															
	Percent Installation orders appointed wiin 3 days	2007 2008					91.56	89.12	92 33	96.16	96.01	95.52	92 38			93,60 93.30
7	Percent Meet Installation Appointments Company Reasons	2007 2008	90%				98.71	99.12	98.51	97.9	96.92	98.25	98.6			97.40 98.29
-	Total Held Orders on Hand - Month end	2007 2008	track				14	11	14	14	13	25	11			27 15
	Held Orders over 30 days	2007 2008	6/mo. *30/25/20				1	2	0	2	2	3	2			. ZI
41	Average <u>Delay Days</u>	2007 2008					6.54	11.78	10.38	6.28	10.84	14.73	15.92			12.13 10.92
-	Number of installation orders	2007 2008		+			12,868	16,676	13,722	11,628	10,561	12,549	16,137			16,432 13,449
54	Access Line Inward Movement per ALIS - located	2007 2008					3,967	3,882	4,370	4,287	4,344	4,691	4,426			64,785 29,967
_																
	pany Accessibility % Toll & Assist answer time within 10 seconds average speed of answer (seconds) % Toll & Assist answer time within 10 seconds average speed of answer (seconds) % Toll & Assist answer time within 10 seconds	2007 2007 2008 2008					1.2 98	1.4 97.5	1.5 97.2	5.4 95.7	1.5 97.3	1.2 97.7	1.2 98.5			3.0 94.8 1.9 97.4
7	% Directory Assistance answer within 10 sec. average speed of answer (seconds) % Directory Assistance answer within 10 sec. average speed of answer (seconds) % Directory Assistance answer within 10 sec.	2007 2007 2008 2008					2.7 95.6	2.1 97.7	2.1 97.9	2.2 96.5	1.2 99.7	1.1 99.7	1.2 99.8			3.7 92.6 1.8 96.1
_	% Repair Service answer within 20 sec. average speed of answer % Repair Service answer within 20 sec. average speed of answer % Repair Service answer within 20 sec.	2007 2007 2008 2008					7.0 93.00	5 92.3	6.2 85	7.1 80.3	6.4 84.5	5.8 93.8	4.4 92.4			5.0 86.9 6.0 88.8
Be	% of calls to a repair number that are abandoned	2007 2008					1.4%	1.3%	1.6%	1.4%	1.5%	1.6%	1.1%			1.4%
Net	work Call Completion	10000						- 71000		7 (27)						
11	Peak Period Central Office Performance	see separa	te report													
Cus	omer Trouble Reports		Objective	Jan	Feb	Mar	Apr	May	June	July	Aug	Sept	Oct	Nov	Dec	YTD Cum.
12	Total Report Rate including subsequents	2007														1.85

		2008	2				1.25	1.17	1.97	2.51	2.37	1.64	1.59	1.79
) o	See Attachment 1 for list of exchanges >2.5						-							
	See Attachment 1 for the of exchanges *2.5													
	Percent Out of Service Cleared within 24 hours													
	(Sundays excluded)	2007										-		68.86
	North	2008					85.07	85.16	69.26	60.40	55.17	74.52	73.70	71.90
	South	2008					86.53	85.17	88.80	71.04	74.18	80.08	73.64	79.92
	Ttoal	2008					85.75	85.17	76.76	64.92	62.05	77.02	73.68	75.05
14	# of Out of Service Cleared within 24 hours													
		2007												4,751
	North District	2008					1,808	1,727	2,829	2,815	2,656	2,020	2,070	2,275
	South District	2008					1,613	1,375	2,314	2,565	2,130	1,780	1,417	1,885
	Total	2008	track				3421	3102	5143	5380	4786	3,800	3,487	4,160
fin.	Average Completion Time for Repairs (hours)	2007	track											24.58
-	realize delighted time for regains (realis)	2008					16.23	17.04	20.25	24.02	25.71	21.63	20.26	20.73
15b	Estimated Average Complition Time for Repair (hours)	2007												21.30
_	(Sundays excluded)	2008					14.02	14.97	16.88	20.80	22.65	17.70	18.32	17.91
40	Connect med manife specialments	2007												79.71
10	Percent met repair appointments North	2007				_	87.80	88.43	83.77	82.46	78.45	84.71	86.96	84.65
	South	2008	90%			_	89.41	87.76	89.47	82.12	81.53	85.15	83.80	85.61
	total	2008					88.61	88.10	86.62	82.30	79.99	84.93	85.38	85.13
	599													
	ALIS	2,007	_				470.000		*****	400.004	444 746	400.000	432,001	517,135 450,779
		2,008					470,222	464,350	456,916	450,231	443,725	438,005	432,001	400,775
	- FairPoint access to this information has been removed and	d we are w	orking to rega	in access to	this informa	ation. Updates wil	be made	when access	is restored.					
-													-	

eld Orders > 30 days										Attachment 2	
25										Item 4	
Jan	Feb	Mar	April	May	June	July	Aug	Sept	Oct	Nov	Dec
2008	2008	2008	2008	2008	2008	2008	2008	2008	2008	2008	2008
			Candia	Candia	Somersworth	Madison	Tamworth	Madison	Somersworth		
			153001.014	Concord	Fitzwilliwms	Raymond	Madison	Meredith	Tamworth		
					Raymond			Tamworth			
					Nashua						

Central	Offices v	with								Attachmen	t1
Customer Trouble Reports > 2.5								Item 12a			
						150					
lan	Feb	Mar	April	May	June	July	Aug	Sept	Oct	Nov	Dec
2008	2008	2008	The state of the s	2008	2008	2008	2008	2008	2008	2008	200
			Hampstead	Pelham	Deerfield	Deerfield	Deerfield	Deerfield	Deerfield		
			Pelham	Rye Beach	New Boston	Bedford	Candia	New Boston	Epsom		
		- 5	Sunapee	Glendale	Milford	Candia	New Boston	Hampstead	Errol		
			Belmont	Errol	Barrington	New Boston	Goffstown	Pelham	Goffstown		
			Rumney	Franconia	Milton Mills	Goffstown	Raymond	Epping	Hampstead		
			100		New Market	Raymond	Atkinson	Kingston	Hampton		
					Rye Beach	Atkinson	Hampstead	Westmoreland	Marlow		
					Seabrook	Hampstead	Pelham	Harrisville	Pelham		
				1 9	Westmoreland	Pelham	Milford	Pittsfield	Pittsburg		
					Cannan	Salem	Barrington	Suncook	Plymouth		
					Enfield	Milford	Kingston	Epsom	Raymond		
					Hanover	Barrington	Milton	Franklin	Suncook		
					Sunapee	Epping	Milton Mills	Center Harbor			
					Lyme	Kingston	Newmarket	Rumney			
				3	Greenville	Milton	Sanbornville	Tamworth			
					Suncock	Milton Mills	Seabrook	Colebrook			
					Danbury	Newmarket	Durham	Errol	Contractor of		
					Ashland	Rye Beach	Portsmouth	Pittsburg	Watch List-Aug.		
					Belmont	Seabrook	Wolfeboro		Canaan		
				1	Center Harbor	Durham	Marlow		Center Sandwich		
					Center Ossipee	Portsmouth	Canaan		Danbury		
				1 3	Center Sandwich	Wolfeboro	Enfiled		Franconia		
					Merideth	Westmoreland	Hanover		Lisbon		
					Rumney	Marlow	Walpole		Lyme		
					Tamworth	Lebanon	Sunapee		Milton Mills		
				5	Warren	Cannan	Lyme		Seabrook		
					Bethlehem	Fitzwilliam	Alstead				
					Colebrook	Hanover	Newport				
					Errol	Walpole	Pittsfield				
					Franconia	Sunapee	Epsom				
				- 3	Jefferson	Lyme	Bristol				
					Lancaster	Charlestown	Penacook				
					Lisbon	Harrisville	Danbury				
					Milan	Alstead	Canterbury				
					N. Stratford	Sullivan	Franklin				
					Pike	Newport	Northwood				

Pittsburg	Greenville	Ashland	
Whitefelld	Rindge	Belmont	
Littleton	Tilton	Center Harbor	
Plymouth	Pittsfield	Center Ossipee	
Groveton	Bristol	Center Sandwich	
	Penacook	Glendale	
	Danbury	Meredith	
	Canterbury	Rumney	
	Franklin	Tamworth	
	Northwood	Weirs Beach	
	Ashland	Bethlehem	
	Belmont	Colebrook	
	Center Harbor	Errol	
	Center Ossipee	Franconia	
	Glendale	Jefferson	
	Meredith	Lisbon	
	Rumney	Milan	
	Tamworth	Pike	
	Weirs Beach	Pittsburgh	
	Colebrook	Twin Mountain	
	Errol	W. Stewartstown	
	Franconia	Whitefield	
	Lisbon	Laconia	
	Milan	Groveton	
	Pittsburg		
	Whitefield		
	Woodsville		

FairPoint Communications Network Improvement Plan- 11/20/08

DEERFIELD

Work is complete for troubles related to the tornado that went through this area. The customers affected have been reconnected to new terminals and will hopefully clear many troubles in this area.

Trouble analysis and field review has identified service improvement work to be started by the **Proact** and **I/M** field forces along Candia Road, Mt. Delight Road and South Road. Aerial closures will be replaced and splices rebuilt at numerous locations. This work will start in November 2008.

EPSOM

One section of wet cable was replaced along New Orchard Road that addressed many troubles in the area.

Several ready-access terminals were replaced along State Highway 4 to correct trouble spots.

A job was identified by the **Proact** group and sent to Engineering Dept. for a work order to replace approximately 3500' of defective buried cable along **Suncook** Valley Highway. Engineering anticipates that the job will be designed and sent to Construction Dept. by 12/15/08.

ERROL

There were three (3) cable jobs completed along Hampshire Woods Road, Akers Pond Road and State Highway 26 to clear various troubles.

There are currently two (2) additional jobs that have been identified and sent along to the Engineering Dept. for review. The job along Colebrook Road calls to replace approximately 5500' of deteriorated cable and the job along State Highway Rte. 16 calls for the replacement of two (2) cables approximately 15,000' each. Engineering Dept is in the process of designing these large jobs and anticipates work to be sent to **Const.** Dept. before the end of this year.

GOFFSTOWN

A wet section of cable along Wallace Road has been replaced which will clear troubles in that area.

The **Proact** Group is in the process of analyzing additional areas and anticipates having more requests in the system by the end of November for Engineering Dept. to review.

HAMPSTEAD

A job along Main St. replaced approximately 400' of a **900x** deteriorated is complete and subsequently corrected many troubles in this area.

An additional request has been submitted by the **Proact** Group to replace approximately 2500' of a wet cable along Wash Pond Road. The Engineering Dept. is now in the process of reviewing this work.

HAMPTON

A job to replace a wet section of cable along Hemlock Haven has been replaced.

The **Proact** Group is in the process of analyzing several other areas to address other known trouble spots. Analysis will be completed in the next few weeks.

MARLOW

There has been work completed along Bain Road that replaced a wet section of cable.

A job also replaced a deteriorated section of cable along Long Pond Road.

Additional analysis is continuing with the **Proact** Group to address trouble areas.

PELHAM

Five (5) jobs are now completed along Jeremy Hill rd., Heritage Road, Sherbourne Road, and Marsh Road that addressed some of the trouble spots.

A job along Brookview Street will replace three (3) deteriorated cables which consist of approximately **1500'** each. This job will be sent to **Const.** Dept. by the end of November.

A job along Nancy Street, Thomas Street and Gladys Street will replace approximately 1800' of three (3) cables. The job will be sent to **Const.** Dept. by the end of November also.

A job along Lane Road has been designed and sent to the **Const.** Dept. They anticipate work to be completed by April 2009 as there are 2 poles involved in this work.

Two (2) other jobs along Mammoth Road and also on Rita Avenue will require analysis by the Engineer as these jobs have just been identified by the **Proact** Group.

PITTSBURG

One section of wet cable has been replaced along Tabor Road that resulted in cleared troubles in the area.

A job along State Highway 3 that will replace approximately 400' of cable has been sent to the Construction Dept. and they anticipate that the work will be completed by Jan. 2009.

PLYMOUTH

A job along Beech Hill Road to replace one wet section of cable will be completed by the Construction Dept. by January 2009.

Approximately 1000' of cable will be replaced along Smith Road to correct the troubles in the area. The job has been sent to the Construction Dept. for review.

A wet cable needs to be replaced along Fairgrounds Road. The job is under review in the Engineering Dept. to be addressed by the end of December 2008.

A job that will address approximately 10,000' of cable along Loon Lake Road is now in the Engineering Dept. for evaluation. The job is expected to go to the **Const**. Dept. by the end of December 2008.

RAYMOND

There is currently a job to address the electronic issues in a SLC system on Beede Hill Road. The job is in the Construction Dept. and is anticipated for a completion by February 2009.

Cable issues along Quail Road will result in an Engineering job to place cable in that area.

A deteriorated cable has been identified in Bill & Ruth's Trailer Park. An Engineeringjob will be issued to replace approximately 850' of cable in that area to correct the troubles.

SUNCOOK

There is analysis by the **Proact** Group in currently underway in this area to address the trouble spots.

WATCH LIST EXCHANGES

CANAAN

A cable along Dorcester Road is in the process of being replaced to correct some trouble areas.

Approximately six (6) sections of cable are being replaced due to high troubles along Orange Pond Road.

There is additional analysis in currently underway in this area to address the trouble spots by the **Proact** Group.

CENTER SANDWICH

The **Proact** Group has repaired two (2) SLC systems that were experiencing high troubles. The electronic cards were replaced in one system and the repeater was fixed for the other system.

A SLC system on Rte. 113 had some powering issues that are in the process of being fixed.

DANBURY

A section of bad cable was replaced along Waukeena Lake Road to correct troubles in the area.

FRANCONIA

A section of cable along State Highway 18 was replaced to correct troubles there.

A section of wet cable along Interstate Highway 93 was replaced also.

LISBON

A job has been completed along State Highway Rte. 117 to replace wet cable in the area.

Another job in the area replaced a bad section of cable between pedestals.

LYME

A cable was replaced along State Highway 113 to the Thetford Elementary School to correct troubles.

A job along River Road will replace five (5) sections of deteriorated cable.

Work is in progress to replace five (5) sections of direct buried cable along Hard Scrabble Road.

The **Proact** group have replaced and repaired splice closures along State Highway Rte 10, Lyme Center Road, and Dorchester Road for a total of nine (9) locations.

The **Proact** Group has also repaired or replaced pedestals along State Highway Rte 10, East Thetford road, and at Vermont Route **113A**.

MILTON MILLS

A job has been engineered to replace approximately 660' of wet cable along Willey Road.

A job has been engineered to replace about 4,000' of wet cable along Lovell Lake Road.

A job to replace about 300' of wet cable along State Highway 16 has been sent to the Construction Dept. for a completion date of 02/10/09.

A job has been requested along Berry Hill Road to replace about 900' of wet cable. The job will be engineered by 12/15/08 and then sent on to the **Const.** Dept.

SEABROOK

The **Proact** Group has placed a new rectifier and upgraded the software in a Litespan system to correct troubles.

A job to replace approximately 200' of cable along Atlantic Avenue is currently underway.

A job is also in progress to replace 350' of cable along Lafayette Avenue to correct troubles in the area.

EXCHANGES FROM SEPT. 2008 LIST

Center Harbor

Work has been completed to repair conductors and a pedestal enclosure in the Linderhof Development and on Bean Road.

A job is requested by the **Proact** Group and sent along to the Engineering Dept. to replace approximately 1,800' of cable along **Kilnwood** Landing.

Epping

A job is in progress to replace nine (9) sections of bad cable along Nottingham Road along with repairing of 3 splice enclosures.

Work is in progress to repair a defective splice on Mast Road.

Work is in progress to repair two (2) terminals and splice enclosures on Exeter Road.

A job is in progress to repair approximately ten (10) sections of cable in a shunt area along Red Oak Hill Road.

Milan

Two (2) SLC systems have been repaired in this area.

A job along Cedar Pond Road will need the replacement of ten (10) poles and nine (9) sections of cable. This job to be completed by March 2009.

State Hwy. 16 has several sections of cable that are currently being analyzed for a future job.

Northwood

Two (2) SLC systems are currently being analyzed due to the new troubles in this area.

A job along State Highway 4 requires the placement of approximately 500' of cable to replace some deteriorated cable. The job is in the Engineering Dept. and should be released by 12/15/08.

Sullivan

The **Proact** Group fixed a splice enclosure on Lead Mine Road to reduce troubles in the area.

A job request to replace about 1,000' of bad cable along Log Cabin Road has been sent to the Engineering Dept. for review.

Westmoreland

The **Proact** Group has rebuilt the cable along South Village Road and Nims Road to correct many trouble spots. The employees worked at approximately 26 pole locations along this route.

Additional analysis is currently being conducted in the Spofford Road and also along Hatt Road for troubles.